



## Replacement Crew Door Rod Assemblies (Forward & Aft versions now available)

### Description


The Transwest Helicopters STC'd Medium Bell Replacement Forward & Aft Crew Door Rod Assemblies replace Aft OEM P/Ns 204-030-481-101 / 001 & 107 and Forward OEM P/N 204-030-483-001/101. The Replacement Crew Door Rod Assembly can be sold with or without the 204-030-499-XXX roller assembly.

### Aircraft Model(s)

Bell 204B, 205A, 205A-1, 205B, 212, 214B, 214B-1, 412, 412CF, 412EP

### Approvals

TCCA STC SH19-36  
FAA STC SR04517NY



### Features

- Manufactured using 4130 chromoly steel rather than OEM aluminum; more durable
- Forward & Aft door rods available

### Benefits

- Cost savings vs. OEM parts
- Readily available
- Reduced maintenance costs
- Greater durability

**Need more information, or have a question?**

Contact us by phone at 1 (250)-498-6691 or email us at [info@transwesthelicopters.com](mailto:info@transwesthelicopters.com)